


EXISTING RAIN AND SNOW
MANAGEMENT ENCOURAGED
WATER ENTRY INTO THE
WALL SYSTEM AT THE
SCUPPER OPENINGS
THEREBY CAUSING
MASONRY DEGRADATION



EXISTING LEAKING
WOOD FRAMED SPIRE

NO DRAINAGE PROVISIONS
UNDER EXISTING SPIRE

EXISTING SPIRE / ROOF CONDITION
