THE ATRIUM

1079 COMMONWEALTH AVE BOSTON, MA

Nathan D. Boutin, P.E.

Senior Project Manager (SE | WAL)

Matthew J. Colturi, CPHC, P.E.

Senior Consulting Engineer (BT | PRU)

1 February 2024





Copyright Materials

This presentation is protected by US and International Copyright laws. Reproduction, distribution, display and use of the presentation without written permission of the speaker is prohibited.



© 2023 Simpson Gumpertz & Heger Inc.




AGENDA

- Introduction
- Background
 - Neighborhood
 - Building History
- SGH Project Timeline
- Structure
- Facade Reclad
- Conclusion and Lessons Learned


INTRODUCTION

Project location
Packard's Corner —



INTRODUCTION | BUILDING OVERVIEW





THREE BUILDINGS



TYPICAL CONCRETE FRAME

INTRODUCTION | BUILDING OVERVIEW




TWO-STORY ADDITION



WOOD-AND-STEEL-FRAMED ADDITION

INTRODUCTION | BUILDING OVERVIEW





OVERALL VIEW



TYPICAL EIFS CLADDING

INTRODUCTION | PROJECT TEAM



Founded 1954 1,500,000sf commercial 5,600 residential units

Owner



Subcontractors

















Exterior Design









Interior Design



Mechanical Design

Crossfield Engineering

INTRODUCTION | SGH TEAM



Current SGH Team



John Porter



Nathan Boutin



Jamil Bhatti



Gary Fay



Jeffry Ceruti



Christopher Grey Matthew Colturi





Syed Najeeb Ullah Husseini

Other SGH Team Members

- **Brett Holland**
- **James Scott**
- Matthew Oostdyk
- **Grant Magnuson**
- Zachary Lozon
- Will Bergendahl
- Benjamin Immonen

- Melissa Hoerber
- Fernanda Brena
- David Zalcman
- Arjun Bir
- Ali Yalaz
- Kayla Seikkula
- Ahmed O.A. Ba Wazir
- Quyen Nguyen
- Michael Barone

INTRODUCTION



Project Objectives


- Condition Assessment
 - Options to extend life
- Make-Safe
 - Remove immediate hazards
 - Allow continued occupancy
- Project prioritization
 - Get things done while planning
- Reclad new lease on life
 - Design phases
 - Construction Administration

Project Challenges

- Helping client evaluate wide range of options
 - Demo to skyscraper
- Significant unforeseen conditions
- Client owner and contractor
- Coordination (multi-faceted)
- Spread thin and leaning on each other

SGH

Over 117 automotive businesses





































































Alvan Fuller 1878








1089 Commonwealth Avenue







Alvan Fuller 1878










Alvan Fuller 1878










Post WW2


- Automotive suburban sprawl
- City congestion
- GI Bill & education (BU)





BACKGROUND | FUTURE AREA DEVELOPMENT







2018 2019 2021 2022 2024 2025

February 2019

- Phone Call
- Falling Concrete
- Train Vibrations
- Failed Repairs








2018 2019 2021 2022 2024 2025

February 2019

- Phone Call
- Falling Concrete
- Train Vibrations
- Failed Repairs







2018 2019 2021 2022 2024 2025

Summer 2019

---> MAKE SAFE











2018 2019 2020 2021 2022 2024 2025

Condition Assessment & Long-term Planning

- Visual and hands-on
- Openings
- Concrete Testing
- Options
 - Repair
 - Reclad
 - New building within
 - Demo
- Cost Collaboration
- Reclad Selected
 - Material Choices
 - Life cycle analysis









Condition Assessment & Long-term Planning

- Options
 - Repair
 - Reclad
 - New building within
 - Demo
- Cost Collaboration
- Reclad Selected
 - Material Choices
 - Life cycle analysis

	BEST Curtain Wall / Pre-Fabricated Unitized Systems / Rain Screen Panel Applications Drainable Panel Systems with desicated airwater berner membrane over sheathing Pressure-equations tableting incorporating vision place.						GOOD Barrier Wall Systems All water managed at surface (no redundancy in field of panel; no sheathing or air/water barrier membrane)		FAIR - NOT RECOMMENDED Modified Drainage Systems Bulk water managed at surface, minnal water nanaged at desicated air/water barrier membrane		
Material / System Trade Name (Common Suppliers)	Aluminum-Framed Unitized Curtain Wall MegaPanel System with one of the claddings to the right. Island, Sanford, IBG	Aluminum Composite Panels Alucobond, Reynobond	Terra Cotta Terra Clad	Fiber Cement Panels Taktyl, FibreC ""Varying degree of quality depending on mfg. process.	Brick Masomy Veneer Tradtional 4 in. brick.	Thin-Brick Veneer Corium, TruBrix "*Not including "tab" systems	Precast Concrete Clark Pacific, BPDL, etc.	Laminate Panels Trespa	Gement Plaster BMI	Drainable EIFS Dryvit, Sto	
General Description	Aluminum framing/mullions infilled with vision and spandrel glazing or metal panels	Two layers of aluminum sheet metal bonded to a thermoset polyethylene plastic core attached with steel or aluminum sub-frame	Terra Cotta (fired clay with glaze coating) panels hung on pre-engineered aluminum clip and sub-girt system	Manufactured sheets of hydraulic cementitious matrices	Solid brick masonry and mortar.	Metal backpan girt system with mechanically engaged thin brick.	Steel-reinforced concrete panels (generally 4"-6" thick).	Wood-based filters and thermosetting realins manufactured under high pressures and temperatures, with hard/durable coatings for protection	Air/water barrer membrane, building paper, metal left, 7/8" cement plaster (3-coat) with option to add drainage composite behind plaster for drainage layer	Waterproofing coating, adhered EPS insulation with drainage grooves, reinforced lamina, acrylic finished coat	
Durability	Best	Best	Best	Good/Fair	Best	Good	Best	Good/Fair	Good	Fair/Poor	
Track Record	Best >40 years	Best >30 years	Best >30 years	Some issues <10 years (US)	Best >50 years	Good <10 years	Best >30 years	Fair <10 years	Fair >30 years	Fair <25 years	
(Can be highly versible depending on the selected system; assumes systems properly environment.)	>40 years	>40 years	>60 years	>20 years	>75 years	>30 years	>75 years	>15 years	>20 years	>15 years	
Construction Duration	Fastest	Good	Good	Good	Slowest	Good	Fastest	Good	Slow	Good	
Dedicated Continuous Air/Water Barrier	Not Required	Required	Required	Required	Required	Required	Not Required	Required	Required	Required	
AinWater Performance	Best	Best	Best	Best	Best	Best	Good	Best	Fair	Fair	
Approximate Weight (PSF)* (including 7 psf for stud framing, interior and exterior sheathing where applicable)	14-23	9	25	9	47	21	50-80	9	17	9	
Triggers NFPA (combustible material)	No	Yes	No	No	No	No	No	Yes	No	Yes	
Option for Continuous Insulation (CI)	N/A	Good	Good	Good	Good	Good	Good	Good	FairiPoor	Good	
Framing/Attachment/Lateral Support	Gravity Load at Floor Slabs	Aluminum or Steel Sub-Girt to Steel Stud Backup Wall	Aluminum or Steel Sub-Girt to Steel Stud Backup Wall	Aluminum or Steel Sub-Girt to Steel Stud Backup Wall	Relieving Angles at Slabs, and ties to Steel Stud Backup Wall	Aluminum or Steel Sub-Girt to Steel Stud Backup Wall	Gravity and Lateral Load at columns	Aluminum or Steel Sub-Girt to Steel Stud Backup Wall	Lath fasteners (and steel sub- girts if Cl included) to Steel Stud Backup Wall	Troweled Adhesive to Steel Stud Backup Wall	
Cladding System Cost	High	Medium	High	Medium	Medium/High	Medium	Medium	Medium	Low	Low	
Glazing System Costs	\$100-125 per s.f. (Schedule Savings if Unitized or Pre-Fabricated)	Aluminum Window/Window Wall (180-100 per s.f.), Storefront Systems (190-85 per s.f.), Punched Cortain Wall (1910-110 per s.f.)					Aluminum Window/Window Wall (\$80-100 per s.f.), Storefront Systems (\$90-95 per s.f.), Punched Curtain Wall (\$100-110 per s.f.)		Aluminum Window/Window Wall (\$80-100 per s.f.), Storefront Systems (\$90-95 per s.f.), Punched Curtain Wall (\$100-110 per s.f.)		
	Crane: Crane or unitizied crane rig off roof required to erect panels.	Crane: No crane required and work could be done off scaffolding.					Crane: Crane required to erect panels into place.	Crane: No crane required and work could be done off scaffolding.	Crane: No crane required and work could be done off scaffolding.		
Constructability Notes	Weight: Could be a potential issue deadloading off slabs.	Weight: Light-weight compared to existing brick masonry cladding system.	Weight: Lighter than existing cladding system.	Weight: Lighter than existing cladding system.	Weight: Comparable to existing cladding weight.	Weight: Light- weight compared to existing brick masonry cladding system.	Weight: Could be a potential issue deadloading off columns.	Weight: Light-weight compared to existing brick masonry cladding system.	Weight: Lighter than existing cladding weight.	Weight: Light-weight compared to existing brick masonry cladding system.	
	Slab Edge Fire Ratings: Will need fire ratings between edge of slab and back of panels (smoke seals).	State State State State National National Adults of state Andreas					Slab Edge Fire Ratings: Will need fire ratings between edge of slab and back of panels (smoke seals).	Slab Edge Fire Ratings: Not required at slab edges.	Stab Edge Fire Ratings: Not required at slab edges.		



2018 2019 2020 2021 2022 2024 2025

Condition Assessment

Garage Rehabilitation

- Slab Reconstruction
- Concrete Repairs
- Coating Replacement
- Plumbing Maintenance



Roof Replacement

- Structural Deck Repairs
- Mechanical Units
- Skylights
- Roof Anchors



2018 2019 2020 2021 2022 2024 2025

Condition Assessment

Roof


Garage



Facade Reclad Design Development

- Architect subconsultant
- Rendering study with owner
- Materials selections





Interior renovations

Facade Reclad Full Scope

- Design Assist
- Interiors and Mechanical
- Construction Administration


GARAGE REHABILITATION



GARAGE REHABILITATION



CONCRETE JOISTS





ONE-WAY SLABS





Fig. 90. Electrically Welded Wire Fabric Reinforcement

(b) Expanded Mesh. Steelcrete. Steelcrete reinforcing fabric a diamond mesh, cold-drawn from a solid steel plate by the Consolid Expanded Metal Companies, Wheeling, W. Va. It possesses many of properties of cold-drawn wire with a guaranteed theoretic elastic limit per cent higher than commercial medium steel.* Steelcrete Mess is from mechanical and welded joints, and provides distribution of reinforment in all directions. It is furnished in large, flat sheets and is much





TWO-WAY SLAB




Fig. 32. Typical Girderless Floor Construction



CORBEL AND COLUMN REPAIRS





LARGE TOPSIDE NEG. MOMENT REPAIRS



FULL-DEPTH SLAB REPAIRS


GARAGE REHABILITATION





BEAM REPAIRS















SPANDREL REPAIRS SNEAK PEAK

FACADE RECLAD



Introduction

- Final Owner Selections
 - Selective Demo to Concrete Frame
 - Metal Panel Reclad w/ new LGMF
 - New Windows and Doors
- Phasing
 - Maximize Occupancy
- Sequencing
 - Access and Demo
 - Concrete and Structural Work
 - Reclad
 - Trailing



EXISTING CONDITIONS

















STRUCTURAL DESIGN

















BUILDING ENCLOSURE DESIGN












BUILDING ENCLOSURE DESIGN | INSULATION





BUILDING ENCLOSURE DESIGN | CURTAIN WALL



Integral flange for perimeter detailing



Panel width and infill variation – vision glass, spandrel, louvers



Double mullion aligns with interior partitions

FACADE RECLAD

OWNER-CONTRACTOR TEAM IS THE CLIENT



OWNER-CONTRACTOR TEAM



Challenges

1. Document management

2. Construction management

3. Contractor's delegation bandwidth

Solutions

Autodesk Docs / BIM360,
 Direct review with subcontractors,
 Contract document revisions

OAC meeting topics,
 Outstanding work and trade coordination,
 Site visit regularity

Diligent fee tracking and projection, Milestone reviews

FACADE RECLAD

COORDINATION AS DESIGNER OF RECORD





Design Iterations – Two Year Rendering Study













COORDINATION | ARCHITECT & OWNER











COORDINATION | ARCHITECT & OWNER






COORDINATION | ARCHITECT & OWNER



Pool Deck at Upper Courtyard



Landscaping at Lower Courtyard



Windows accommodate interior ceilings and walls, and mechanical requirements



Louver for mechanical plenum above ceilings

11' ceiling height at living rooms


8' ceiling height at living rooms


Align opaque wall and double wide mullion with interior partitions

COORDINATION | OUR FUTURE SELVES




Parapet for Roof Assembly Thickness and Future Facade








Façade Design Accommodates Existing Conditions







EXISTING BUILDING


CODE COMPLIANCE REVIEW











EXISTING BUILDING

RETAIL ENTRANCES





EXISTING BUILDING

NONRESIDENTIAL SPACES











EXISTING BUILDING

HISTORIC ARCHITECTURAL FEATURES







EXISTING BUILDING

MAIN ENTRY


FACADE RECLAD BIM CHALLENGES





Scanning and Model Development

- Existing drawings ca. 1920s and 1980s
- Lidar scanning by Bimstream (formerly Aerial Genomics) of existing building
- Point cloud interpreted by modeler and converted into Revit
- Level of detail (LOD)








LIDAR SCANNING AND BIM



Building Model Challenges

- Scanning performed prior to demolition
- Modeled components (walls, floors, parts)
- Architect owns modeling, SGH owns detailing
- Columns not modeled on column grid
- Solution: Reference planes!




DRAFTER'S POINT OF VIEW




Reference Planes:

= existing structure reference plane

= face of cladding reference plane






DRAFTER'S POINT OF VIEW



Reference Planes:



OH %*@#& MOMENTS... THEY COME FULL CIRCLE



Phase 1 (CD Set due August 8)

August 7, 2020 4:02 pm

To: Matthew Colturi

Subject: 1079

It seems like somewhere along the way this afternoon the exterior wall on the alley side got deleted. We luckily had a local file that he hadn't sync'd yet so we are saving out his local file and are going to try and copy the wall and all the windows back into the cloud model.

I'm not sure when the last time you sync'd was but if we can't copy the wall, we may need to overwrite the cloud model. Fingers crossed. I'll keep you posted.

Phase 3 (Permit Set due August 11)

August 7, 2023 10:06 pm


From: Matthew Colturi

Subject: 1079 MODEL – DELETED FLOOR

Did someone delete Level 4C completely from the model? I am not seeing any floors, windows, walls, or doors at this Level of Building 2 – see elevations A3-205 and A3-208, and associated wall sections and details.

POST DEMO SURVEY & FIELD LAYOUT







024119 Selective Demolition

- B. After completion of selective demolition, provide a field verification survey of the existing structure to document the existing structural concrete framing and other existing structural elements to remain within the work extents.
 - Survey shall be performed by a surveyor licensed in the Commonwealth of Massachusetts, including the following minimum survey data:

Vertical (openings)

→ Top and bottom elevations of beams at both ends (where they intersect columns) and every 5 ft max along their length.

Horizontal (columns)


Side faces and centerline of columns at each floor level.


Depth (structural backup)


Exterior face of columns at each floor level.

Exterior face of all concrete beams at both ends (where they intersect with columns) and every 5 ft max along their length.

- e. Floor slab elevations.
- Roof and top of parapet elevations.
- g. Door threshold elevations.
- Dimensions for openings to remain.
- Provide plan and elevation drawings, showing the results of the field verification survey and using the Contract Drawings as a background showing the required information.








"You're right, it is easier said than done. That's why I said it; because it's easy. Try and keep up."

POST DEMO SURVEY & FIELD LAYOUT



How it's going

- Phase 1 Land surveyor attempted
 - Field measurements
 - No control → significant delays
- Phase 2 Full survey provided by lidar scan-
 - Survey data interpretation
 - Conflicting survey and site control info
 - Significant delay
- Phase 3 To be performed
- LESSON: Establish building control with contractor as early as possible



FUTURE RECLAD PROJECTS



Lessons Learned and Tips for Future Success

- Initial Model Development:
 - Establish site control
 - Set model expectations
- General:
 - BIM workflow and roles
 - Revit model linking
 - Drawings for phased projects
- Design Recommendations:
 - Wall assembly depths and survey
 - Working points

FACADE RECLAD STRUCTURAL REPAIRS



Unique Repair Conditions – Beam Repairs








SGH


Unique Repair Conditions – Original Roof Deck












SGH


Unique Repair Conditions – Corner Column





Unique Repair Conditions – Corner Column









Unique Repair Conditions – Slab Reconstruction



Quotation

QE23-045

To:

1079 Commonwealth Ave Simpson, Gumpertz & Heger 800 Boylston Street Suite 2320 Boston, MA 02199

Phone: (781) 267-5513



Headed Reinforcement Corp. EAST

402 Vulcan Street, Suite 104

Buffalo, NY 14207

Tel: 716-983-1545

ed@hrc-usa.com

www.hrc-usa.com

Quote Date: 11/17/2023

Project: 1079 Commonwealth Ave







CONCLUSIONS OVERARCHING LESSONS



CONCLUSIONS

- Tackle Exciting Project
 - Moving parts
 - Large Teams (SGH prime)
- Handle many surprises
- New life to an old structure for decades of future use
 - Sustainability
- Combined Contractor and Owner
- BT and SE lean on and learn from each other
- Modeling lessons for old structures
- Fee management cradle to grave
 - All from one phone call
 - o \$2.5M
 - Several other major projects



