

Children's Health Bright Building and SkyBridge Exterior Facade Repairs 1935 Medical District Drive Dallas, TX 75235







CLIENT:

Children's Medical Center 1935 Medical District Drive Dallas, TX 75235

WJE Job Number: 2020.2093.1

ARCHITECTS AND ENGINEERS:



Wiss, Janney, Elstner Associates, Inc. 6363 N. State Highway 161, Suite 550 Irving, Texas 75038

August 19, 2021

Sheet List Table

Sheet Number	Sheet Name
G-001	Cover Sheet
G-101	General Notes and Site Plan
Bright Building	
A-101-BB	Bright Building - Roof Plan
A-201-BB	Bright Building - North, East Elevations
A-202-BB	Bright Building - South, West Elevations
A-501-BB	Bright Building - Details
A-502-BB	Bright Building - Details
SkyBridges	
A-101-SB	SkyBridge - Roof Plan
A-201-SB	SkyBridge A - Elevations
A-202-SB	SkyBridge B - Elevations
A-301-SB	Hospital, Employee Parking Garages - Partial Elevations
A-501-SB	SkyBridge - Details
A-502-SB	SkyBridge - Details


FOR CONSTRUCTION

ENGINEERS
ARCHITECTS
MATERIALS SCIENTISTS

Wiss, Janney, Elstner Associates, Inc. 6363 N. State Highway 161, Suite 550 Irving, Texas 75038 972.550.7777 tel | 972.550.7770 fax

Headquarters & Laboratories: Northbrook, Illinois
Atlanta | Austin | Boston | Chicago | Cleveland | Dallas | Denver | Detroit
Honolulu | Houston | Los Angeles | Minneapolis | New Haven | New York
Philadelphia | Princeton | San Francisco | Seattle | South Florida | Washington, D.C

TEXAS REGISTERED ENGINEERING FIRM F-0093




Consultar

Proje

Children's Health Bright Building and SkyBridge
Exterior Facade Repairs
1935 Medical District Drive
Dallas, TX 75235

Clier

Children's Medical Center 1935 Medical District Drive Dallas, TX 75235



G-001


ENGINEER.


GENERAL NOTES

- VERIFY ALL DIMENSIONS AND CONDITIONS IN FIELD. DO NOT SCALE DRAWINGS. DIMENSIONS SHOWN ON THE DRAWINGS ARE TAKEN FROM THE ORIGINAL CONSTRUCTION DOCUMENTS AND ARE PROVIDED FOR
- 2. THIS DRAWING SET IS INTENEDED TO BE PRINTED IN COLOR.
- 3. VERIFY ALL QUANTITIES. QUANTITIES SHOWN ARE FOR ESTIMATING PURPOSES ONLY.
- 4. COORDINATE REQUIREMENTS AND PROVIDE PROOF OF INSURANCE PRIOR TO THE START OF WORK.
- VERIFY EXISTING PLUMBING AND ELECTRICAL LINES AND EQUIPMENT THAT WILL BE ACCESSED AS PART OF WORK PERFORMED. THE CONTRACTOR SHALL PROVIDE ALL NECESSARY EQUIPMENT, LABOR, MATERIALS, AND COMPONENTS REQUIRED FOR THE TEMPORARY RELOCATION OF MECHANICAL/ELECTRICAL EQUIPMENT AND PLUMBING LINES DURING THE REPAIR WORK.
- SECURE AND PAY FOR ALL PERMITS, LICENSES AND GOVERNMENT FEES AS REQUIRED. THE CONTRACTOR SHALL COMPLY WITH CODES, ORDINANCES, RULES, REGULATIONS, ORDERS AND OTHER LEGAL REQUIREMENTS OF PUBLIC AUTHORITY, WHICH BEAR ON THE PERFORMANCE OF THE WORK.
- PROMPTLY SUBMIT VERBAL AND WRITTEN NOTICE TO THE ENGINEER OF OBSERVED VARIANCE OF THE CONTRACT DOCUMENTS FROM ACTUAL ON-SITE CONDITIONS.
- SUPPLY THE OWNER WITH SAFETY DATA SHEETS (SDS) FOR EACH CHEMICAL THAT WILL BE BROUGHT ONTO THE JOB SITE AND SHALL COMPLY WITH THE REQUIREMENTS OF THE OSHA HAZARD COMMUNICATION
- SUBMIT DEMOLITION AND CONSTRUCTION SCHEDULES TO THE OWNER AND ARCHITECT/ENGINEER FOR APPROVAL PRIOR TO COMMENCING WORK.
- 10. THE PRODUCTS SPECIFIED ARE BELIEVED TO HAVE PROPERTIES ADEQUATE FOR SUCCESSFUL COMPLETION OF THE WORK. IF THE CONTRACTOR HAS FOUND THESE PRODUCTS TO BE UNACCEPTABLE OR HAS HAD DIFFICULTY USING THESE MATERIALS, THE CONTRACTOR SHALL IMMEDIATELY INFORM THE ENGINEER.
- 11. CONTRACTOR IS RESPONSIBLE FOR MEANS AND METHODS OF THE REPAIR WORK.
- 12. WISS, JANNEY, ELSTNER ASSOCIATES, INC. (WJE) SHALL NOT HAVE CONTROL OVER OR CHARGE OF AND SHALL NOT BE RESPONSIBLE FOR CONSTRUCTION MEANS, METHODS, TECHNIQUES, SEQUENCES OR PROCEDURES, OR FOR SAFETY PRECAUTIONS AND SAFETY PROGRAMS IN CONNECTION WITH THE PROJECT. SINCE THESE ARE THE RESPONSIBILITY OF OTHERS, WJE SHALL NOT BE RESPONSIBLE FOR THE CONTRACTOR'S SCHEDULES OR FAILURE TO CARRY OUT THE PROJECT IN ACCORDANCE WITH CONTRACT DOCUMENTS. WJE SHALL NOT HAVE CONTROL OVER OR CHARGE OF ACTS OR OMISSIONS OF THE CONTRACTOR, SUBCONTRACTORS, OR THEIR AGENTS OR EMPLOYEES, OR OF ANY OTHER NON-WJE PERSONS PERFORMING PORTIONS OF THE PROJECT.
- 13. CONTRACTOR IS SOLELY RESPONSIBLE FOR ALL JOB SAFETY DURING THE REPAIR WORK.
- 14. DEMOLITION REQUIRED SHALL PROCEED ONLY AT THE DIRECTION OF THE OWNER ACCORDING TO SCHEDULES AS MUTUALLY AGREED UPON. PROVIDE ALL TEMPORARY CONTROLS AS NECESSARY TO ALLOW FOR THE BUILDING OPERATIONS.
- 15. LIMIT ON-SITE STORAGE OF MATERIALS TO THOSE AREAS IDENTIFIED BY THE OWNER. DO NOT UNREASONABLY ENCUMBER SITE WITH MATERIALS OR EQUIPMENT. THE MATERIALS AND EQUIPMENT SHALL BE CONFINED TO THE AREAS INDICATED IN THE CONTRACT DOCUMENTS OR BY THE DIRECTION OF THE OWNER OR ARCHITECT/ENGINEER. DO NOT LOAD STRUCTURE WITH WEIGHT THAT WILL ENDANGER STRUCTURE. CONTRACTOR SHALL ASSUME FULL RESPONSIBILITY FOR THE PROTECTION AND SAFEKEEPING OF PRODUCTS STORED ON PREMISES. MOVE ANY STORED MATERIAL OR PRODUCTS WHICH INTERFERE WITH OPERATIONS OF THE OWNER. STORE MATERIAL ONLY IN AREAS PROVIDED BY THE
- 16. WATER AND ELECTRICITY MAY BE TAKEN FROM BUILDING FOR CONSTRUCTION PURPOSES ONLY AT AREAS IDENTIFIED ACCEPTABLE BY THE OWNER. TOILET FACILITIES IN BUILDING SHALL NOT BE USED BY THE
- 17. PROVIDE AND MAINTAIN REQUIRED DUST BARRIERS, CANOPIES, BARRICADES, PROTECTION AND WARNING LIGHTS IN GOOD CONDITION UNTIL THE COMPLETION OF THE WORK REQUIRING SUCH PROTECTION AND THEN REMOVE THE SAME. ALL EXTERIOR CANOPIES AND BARRICADES SHALL COMPLY WITH FEDERAL, STATE AND LOCAL LAWS AND REGULATIONS. ALL INTERIOR BARRIERS AND PROTECTION SHALL COMPLY WITH CHILDREN'S HEALTH REQUIREMENTS AND PROCEDURES.
- 18. MAINTAIN PREMISES FREE FROM ACCUMULATIONS OF WASTE MATERIAL AND RUBBISH.
- 20. PROTECT GROUNDS AND LANDSCAPING WHEN PERFORMING WORK. THE CONTRACTOR WILL BE RESPONSIBLE FOR DAMAGE TO GROUNDS AND LANDSCAPING AND BE REQUIRED TO REPAIR OR REPLACE
- 21. COMPLY WITH ALL SECURITY PROCEDURES.
- 22. COSTS INCURRED BY THE OWNER BY ILL-TIMED WORK, DEFECTIVE WORK OR WORK NOT CONFORMING TO THE CONTRACT DOCUMENTS, ARE THE RESPONSIBILITY OF THE CONTRACTOR.
- 23. PROVIDE SHORING, BRACING AND SUPPORT AS REQUIRED TO MAINTAIN THE STRUCTURAL INTEGRITY OF THE NEW OR EXISTING CONSTRUCTION DURING THE WORK. CONSTRUCTION DEBRIS SHALL BE REMOVED IN A MANNER THAT AVOIDS OVERLOADING ADJACENT STRUCTURAL MEMBERS.
- 24. DO NOT STOCKPILE CONSTRUCTION MATERIAL IN A MANNER THAT WILL OVERLOAD OR EXCEED THE CAPACITY OF THE STRUCTURAL MEMBERS.
- 25. THE CONTRACTOR AND HIS RESPECTIVE SUBCONTRACTORS SHALL EACH HAVE FIVE OR MORE YEARS EXPERIENCE PERFORMING REPAIR WORK SIMILAR IN SIZE, TYPE, AND COMPLEXITY TO WHAT IS SHOWN IN THE CONTRACT DOCUMENTS.
- 26. ENFORCE STRICT DISCIPLINE AND GOOD ORDER AMONG EMPLOYEES. DO NOT EMPLOY UNFIT PERSONS OR PERSONS NOT SKILLED IN THE ASSIGNED TASK.
- 27. WHERE A DETAIL IS SHOWN FOR ONE CONDITION, IT SHALL APPLY FOR ALL LIKE OR SIMILAR CONDITIONS, EVEN THOUGH NOT SPECIFICALLY MARKED ON THE DRAWINGS.
- 28. ALL CONSTRUCTION SHALL BE SUBJECT TO REVIEW BY THE ENGINEER BEFORE IT IS CONCEALED FROM VIEW. COORDINATE EXPECTED REVIEW ITEMS WITH THE ENGINEER PRIOR TO THE START OF CONSTRUCTION AND PROVIDE REASONABLE NOTIFICATION TO THE ENGINEER TO ALLOW FOR SUCH REVIEW AS THE WORK PROCEEDS.
- 29. REMOVE AND DISPOSE OF IN A PROPER MANNER (OFF-SITE) ALL EXISTING MATERIAL REMOVED FROM THE BUILDING DURING THE COURSE OF THE WORK ON A DAILY BASIS. REMOVAL AND DISPOSAL SHALL BE SATISFACTORY TO THE ARCHITECT/ENGINEER AND OWNER.
- COORDINATE USE OF PREMISES UNDER THE DIRECTION OF THE OWNER. TEMPORARY DISRUPTIONS TO THE USE OF THE BUILDING BY EMPLOYEES AND PUBLIC, INCLUDING NOISE, DUST AND DISRUPTION OF UTILITIES, SHALL BE COORDINATED A MINIUMUM OF 48 HOURS IN ADVANCE AND APPROVED BY THE OWNER. CONTRACTOR WORK NOT COORDINATED IN ADVANCE WHICH CAUSES DISRUPTIONS TO THE USE OF THE BUILIDNG BY EMPLOYEES AND PUBLIC MAY BE STOPPED BY THE OWNER AND SHALL NOT BE COMMENCED AGAIN UNTIL PROPER COORDINATION IS ACHIEVED. CONTRACTOR SHALL BE RESPONSIBLE FOR ALL COSTS RESULTING FROM WORK STOPPAGES OR DELAYS CAUSED BY CONTRACTORS LACK OF COORDINATION WITH THE OWNER.
- CONTRACTOR SHALL BE RESPONSIBLE FOR MAINTAINING THE WATER TIGHTNESS OF THE AREAS OF THE BUILDING BEING WORKED ON DURING THE COURSE OF THE WORK. PROVIDE TEMPORARY PROTECTION OF THE EXISTING CONSTRUCTION FROM THE WEATHER UNTIL REMOVED PORTIONS ARE COMPLETELY REPLACE WITH NEW CONSTRUCTION. THE COST OF DAMAGE AND REPAIRS SHALL BE MADE AT NO COST TO THE
- 32. THESE DRAWINGS AND SPECIFICATIONS APPLY TO THE PROJECT INDENTIFIED IN THE TITLEBLOCK ONLY
- IN THE EVENT OF CONFLICT BETWEEN THE DRAWINGS AND THE SPECIFICATIONS, THE MORE STRINGENT REQUIREMENT AND BETTER QUALITY SHALL GOVERN UNLESS WRITTEN NOTIFICATION IS PROVIDED BY THE

AND SHALL NOT BE USED FOR ANY OTHER PURPOSE WITHOUT THE EXPRESSED WRITTEN CONSENT OF WJE.

- 34. CONTRACTOR TO OBTAIN BADGES FOR ALL ONSITE PERSONNEL THROUGH VENDORMATE CREDENTIALING SERVICE. BADGES REQUIRE CURRENT FLU SHOTS AND TUBERCULOSIS TESTS AT THE EXPENSE OF THE
- 35. COMPLY WITH ALL OSHA REGULATIONS REGARDING EXPOSURE AND CAPTURE OF SILICA DUST FOR WORK RELATED TO GRINDING AND ROUTING OF CEMENTITIOUS MATERIALS.







FOR CONSTRUCTION

Wiss, Janney, Elstner Associates, Inc. 6363 N. State Highway 161, Suite 550 Irving, Texas 75038 972.550.7777 tel | 972.550.7770 fax

Headquarters & Laboratories: Northbrook, Illinois Atlanta | Austin | Boston | Chicago | Cleveland | Dallas | Denver | Detroit Honolulu | Houston | Los Angeles | Minneapolis | New Haven | New York Philadelphia | Princeton | San Francisco | Seattle | South Florida | Washington, D.0

www.wje.com


TEXAS REGISTERED ENGINEERING FIRM F-0093



Consultants

Children's Health Bright Building and SkyBridge Exterior Facade Repairs 1935 Medical District Drive Dallas, TX 75235


Children's Medical Center 1935 Medical District Drive Dallas, TX 75235





General Notes and Site Plan

Sheet Title

G-101







ENGINEERS
ARCHITECTS
MATERIALS SCIENTISTS

Wiss, Janney, Elstner Associates, Inc. 6363 N. State Highway 161, Suite 550 Irving, Texas 75038 972.550.7777 tel | 972.550.7770 fax

www.wje.com

Headquarters & Laboratories: Northbrook, Illinois

Atlanta | Austin | Boston | Chicago | Cleveland | Dallas | Denver | Detroit

Honolulu | Houston | Los Angeles | Minneapolis | New Haven | New York

Philadelphia | Princeton | San Francisco | Seattle | South Florida | Washington, D.0

TEXAS REGISTERED ENGINEERING FIRM F-0093




Consultants

Proje

Children's Health Bright Building and SkyBridge Exterior Facade Repairs 1935 Medical District Drive Dallas, TX 75235

Clier


Children's Medical Center 1935 Medical District Drive Dallas, TX 75235





Bright Building - South,
West Elevations


Sheet Title


A-202-BB


























Wiss, Janney, Elstner Associates, Inc. 6363 N. State Highway 161, Suite 550 Irving, Texas 75038 972.550.7777 tel | 972.550.7770 fax

www.wje.com

Headquarters & Laboratories: Northbrook, Illinois


Atlanta | Austin | Boston | Chicago | Cleveland | Dallas | Denver | Detroit Honolulu | Houston | Los Angeles | Minneapolis | New Haven | New York Philadelphia | Princeton | San Francisco | Seattle | South Florida | Washington, D.C.

TEXAS REGISTERED ENGINEERING FIRM F-0093



and SkyBridge Exterior Facade Repairs 1935 Medical District Drive Dallas, TX 75235

Children's Medical Center 1935 Medical District Drive Dallas, TX 75235



SkyBridge - Details

A-501-SB

n from Wiss, Janney, Elstner Associates, Inc. (WJE). WJE disclaims any responsibility for its unauthorized us > NEW BACKER ROD AND — SEALANT JOINT WITHIN OPEN JOINT BETWEEN THE FIXED AND OPERABLE WINDOW FRAME



Sealant Repair at Open Window Joint

SCALE: 3" = 1'-0"

REMOVE AND REPLACE INTERIOR DRYWALL
(APPROXIMATELY 15 SQUARE FEET) TO ALLOW
VISUAL ACCESS TO THE BACK OF THE WINDOW
SYSTEM BEHIND. THIS OPENING WILL NEED TO
BE COORDINATED WITH WATER INTRUSION
TESTING BY WJE. AFTER COMPLETION OF WATER
INTRUSION TESTING, WJE WILL PROVIDE
SUPPLEMENTAL REPAIR DETAILS TO ADDRESS
IDENTIFIED DEFICIENCIES WITHIN THE WINDOW
SYSTEM.


IDENTIFIED DEFICIENCIES WITHIN THE WINDOW
SYSTEM.
FOLLOW NECESSARY ICRA BARRICADE
REQUIREMENTS DURING
REMOVAL/REPLACEMENT OF INTERIOR FINISHES.



Drywall Removal for Water Testing at SkyBridge C


SCALE: 3" = 1'-0"

REMOVE AND REPLACE DRYWALL FINISHES
AND SPANDREL INSULATION IN ORDER TO
REPLACE BROKEN SPANDREL LITE. FOLLOW
NECESSARY ICRA BARRICADE REQUIREMENT
DURING REMOVAL/REPLACEMENT OF
INTERIOR FINISHES AND GLASS. REPLACE
SPANDREL INSULATION WITH SIMILAR TYPE




Drywall Removal for Spandrel Replacement - Interior View

REMOVE AND REPLACE FAILED IG UNIT
WITH SIMILAR TYPE, AS APPROVED BY
DESIGNER. CONTRACTOR TO VERIFY GLASS
TYPE, THICKNESS AND D.L.O. IN FIELD
PRIOR TO ORDERING REPLACEMENT.
FOLLOW NECESSARY ICRA BARRICADE
REQUIREMENTS DURING GLASS
REPLACEMENT



C6 IG Unit Replacement Detail

REMOVE AND REPLACE BROKEN SPANDREL GLASS UNIT (APPROXIMATELY XX SQUARE FEET) WITH SIMILAR TYPE, AS APPROVED BY DESIGNER. REMOVAL OF INTERIOR FINISHES (AS SHOWN IN DETAIL A3/A-502-SB) WILL BE REQUIRED TO REGLAZE SPANDREL UNIT. CONTRACTOR TO VERIFY GLASS TYPE, THICKNESS AND D.L.O. IN FIELD PRIOR TO ORDERING REPLACEMENT. FOLLOW NECESSARY ICRA BARRICADE REQUIREMENTS DURING REMOVAL/REPLACEMENT OF INTERIOR FINISHES AND GLASS PLACEMENT.



Spandrel Replacement Detail - Exterior View

SCALE: 3" = 1'-0"

FOR CONSTRUCTION

ENGINEERS
ARCHITECTS
MATERIALS SCIENTISTS

Wiss, Janney, Elstner Associates, Inc. 6363 N. State Highway 161, Suite 550 Irving, Texas 75038 972.550.7777 tel | 972.550.7770 fax

www.wje.com

Headquarters & Laboratories: Northbrook, Illinois

Atlanta | Austin | Boston | Chicago | Cleveland | Dallas | Denver | Detroit

Honolulu | Houston | Los Angeles | Minneapolis | New Haven | New York

Philadelphia | Princeton | San Francisco | Seattle | South Florida | Washington, D.C.

TEXAS REGISTERED ENGINEERING FIRM F-0093




Consultants

Project

Children's Health Bright Building and SkyBridge Exterior Facade Repairs 1935 Medical District Drive Dallas, TX 75235

Client

Children's Medical Center 1935 Medical District Drive Dallas, TX 75235



SkyBridge - Details

Sheet Title

A-502-SB